

three inches = one foot
one and one half inches = one foot
one inch = one foot
three quarters inch = one foot
one half inch = one foot
one quarter inch = one foot
one eighth inch = one foot



P71 EAST EDGE OF FRONT ENTRY PORCH C-WING (SOUTH SIDE)



P77 EAST EDGE OF ROOF OVER ENCLOSED PORCH AT SOUTH END OF B-WING



P83 WEST SIDE OF LOW-SLOPE ROOF AREA 'E1-A' (LOOKING SOUTH)



P89 AERIAL VIEW OF B-WING (LOOKING NORTHWEST)



P95 EXTERIOR PARAPET OF ROOF 'E5' ON NORTH SIDE OF C-WING [REFER TO SHEET A100]



P101 LOW-SLOPE ROOF 'E8' ON NORTH SIDE OF B-C CONNECTOR (LOOKING SOUTH) [SEE SHEET A100]




P72 EAST EDGE OF FRONT ENTRY PORCH C-WING (SOUTH SIDE)



P78 SOUTH EDGE OF ROOF OVER ENCLOSED PORCH AT SOUTH END OF B-WING



P84 WEST SIDE OF B-WING (LOOKING NORTH)



P90 ENLARGED AERIAL VIEW OF CONDITIONS ABOVE (LOOKING NORTH)



P96 LOW-SLOPE ROOF 'E5' ON NORTH SIDE OF C-WING [REFER TO SHEET A100]




P102 AERIAL VIEW INTO COURTYARD ON NORTH SIDE OF C-WING [CONTEXT PHOTO]



P73 EAST EDGE OF FRONT ENTRY PORCH C-WING [ENLARGED PHOTO OF CONDITIONS ABOVE]



P79 GUTTER END ADJACENT TO ROOF OVER ENCLOSED PORCH AT SOUTH END OF B-WING



P85 AERIAL VIEW OF B-WING (SOUTH END OF ROOF)



P91 WEST SIDE OF LOW-SLOPE ROOF AREA 'E1-A' (LOOKING SOUTH)



P97 ROOFS 'E1', 'E2' AND 'E3' ON NORTH SIDE OF C-WING [REFER TO SHEET A100]



P103 VIEW FROM ROOF 'E5' ON NORTH SIDE OF C-WING (LOOKING EAST) [CONTEXT PHOTO]



P74 LOW-SLOPE ROOF AREAS BEHIND C-WING



P80 COMPOUND HIP ROOF CONDITION AT SOUTH END OF B-WING



P86 WEST SIDE OF B-WING (LOOKING NORTH)




P92 EXTERIOR VIEW OF CONDUCTOR BOX REFERENCED IN PHOTO ABOVE



P98 VIEW FROM ROOF 'E5' ON NORTH SIDE OF C-WING (LOOKING SOUTH) [CONTEXT PHOTO]



P104 COMPOUND EAVE CONDITION ON WEST SIDE OF D-WING



P75 ADDITION AT WEST SIDE OF C-WING (SOUTH)



P81 WEST SIDE OF LOW-SLOPE ROOF AREA 'E1-A' (LOOKING NORTH) [REFER TO SHEET A100]




P87 AERIAL VIEW OF B-WING (LOOKING NORTHWEST)



P93 LOW-SLOPE GRAVEL BALLAST ROOF 'E2' ON NORTH SIDE OF C-WING [REFER TO SHEET A100]




P99 AERIAL VIEW OF B-WING (LOOKING SOUTH) FROM ROOF 'E5' [CONTEXT PHOTO]



P105 EAVE CONDITION ON WEST SIDE OF D-WING



P76 VIEW OF C-WING (SOUTH) FROM SOUTHWEST [CONTEXT PHOTO]



P82 WEST SIDE OF LOW-SLOPE ROOF AREA 'E1-A' (LOOKING SOUTH)



P88 ENLARGED AERIAL VIEW OF CHIMNEY CAP ABOVE (LOOKING NORTHWEST)




P94 EXTERIOR PARAPET OF ROOF 'E5' ON NORTH SIDE OF C-WING [REFER TO SHEET A100]




P100 LOW-SLOPE ROOF AREA 'E1-A' (LOOKING NORTH) [REFER TO SHEET A100]

100% CONSTRUCTION DOCUMENTS

ADDENDUM No 1	05-08-13
Revisions:	Date



Dept. of Veterans Affairs
Medical Center
5000 W. National Avenue
Milwaukee, WI



CONSULTANTS:

PROJECT LEADER:

CHEQUAMEGON BAY ENGINEERING, INC.
© 2012-2013

ASHLAND, WI
211 6TH STREET WEST
ASHLAND, WI 54806
PHONE: (715) 682-4004
FAX: (715) 682-4005

MILWAUKEE, WI
923 N. MAYFAIR ROAD,
SUITE 100
MILWAUKEE, WI 53208
PHONE: (414) 258-8004
FAX: (414) 258-8154

Drawing Title
Existing Roof Photographs
w New Work Scope Notes

Approved: Project Director

Project Title
Building No. 6 - Re-roof

Location
VA Medical Center, Milwaukee, WI

Date
5 April 2013

Checked By:
NJM

Drawn By:
NJM

Project Number
695-12-188

Building Number
6

Drawing Number
A302

Office of
Facilities
Management

Department of
Veterans Affairs